
Release of the SW 7.37

Herewith the Software 7.37 for the ICT Systems 46 / 88 / 880 is released.

The SW 7.37 is exclusively a Bug-fix Release, please see the contents in the following table.



Important remark:

With update from a SW older than 7.34 to 7.37 generally the system will be set to the delivery state. In advance, please save the config. Data and backup them after update of the firmware!

If a SW 7.34 is already installed, no delivery state will be established.

Firmware ICT 46

File: ICT46_V7.37 RC02

Firmware ICT 88

File: ICT88_V7.37 RC02

Firmware ICT 880 (rack)

File: ICT880_V7.37 RC02

Firmware GW

File: ICT GW_V7.36 RC02

WIN-Tools

File: 7.31

List of bug fixing and changes from Release 7.31 to Release 7.32

Nr.	Changes / Bugfixing
SIP adjustments	
	Bugfix ICT 46 / 88 / 880: Coupled systems via VPN: it could happen, that no ringtone was established when a call to system 1 (with automatic answer by Voice Applikation - Auto Attendant) was transferred by the application to system 2
	Bugfix ICT 880: Very seldom freezing of Up0-interfaces on the expansion module XT caused by extreme external influences (Bursts) via the network (230 V and telephonenet)
	Bugfix ICT 880: Improved RESET behaviour of the whole system, in case of reset of the expansion module
	Bugfix ICT 880: New diagnose-entry, in case of expansion Reset
System	
WIN – Tools	
VoVPN – Gateway	
System-telephones	
Export	
New functions	
DECT	
Trunk lines	
Other telephones	
Network	

	Service
	Applications
	General Details
	Still open – but known problems
	Advice to additional informations in the FAQ area on the FEC Homepage