

Release of software version 7.6.7

Herewith the software version 7.6.7 for the PBX systems ICT 46/88 and 880 is released for external use. Release 7.6.7 is a bug fixing release based on release 7.6.6. Please see the content in the following table.

firmware elmeg ICT 46

file: ICT46_v7.67_rc03.fwr

firmware elmeg ICT 88

file: ICT88_v7.67_rc03.fwr

firmware elmeg ICT 880 (rack)

file: ICT880_v7.67_rc03.fwr

WIN-Tools

No changes, please use file WIN-Tools-ICT-V762-INT_090811.exe

List of new features, changes and bug fixing from release 7.6.6 to release 7.6.7:

No.	Bug fixing
System	
01	Bug fix: ARS 13940 / 14724 (ICT 46, ICT 88 and ICT 880) Keypad will cut after 27 Keys. This problem is fixed.
02	Bug fix: ARS 14847 (ICT 46, ICT 88 and ICT 880) Polycom Handsets with new IPEI (05003) are not supported. This problem is fixed.
TAPI	
01	Bug fix: ARS 14227 / 14270 (ICT 46, ICT 88 and ICT 880) No Answering by TAPI possible for calls initiated by transfer functions. This problem is fixed.
02	Bug fix: ARS 14314 (ICT 46, ICT 88 and ICT 880) Reactivating a parked connection by TAPI is not possible. This problem is fixed.