

Release of software version 7.5.4

Herewith the software version 7.5.4 for the PBX systems T240/T444 and T484 is released for external use. Release 7.5.4 is a bug fixing release based on release 7.5.3 Please see the content in the following table.

firmware elmeg T240

file: T240_v754_rc01.fwr firmware elmeg T444 file: T444_v754_rc01.fwr firmware elmeg T484

file: T484_v754_rc01.fwr

WIN-Tools

No changes, please use file WIN-Tools-Txxx-V751-INT_080611

List of changes and bug fixing from release 7.5.3 to release 7.5.4:

No.	Bug fixing
System	
01	Bug fix: ARS 13898 (T240,T444,T484) Sporadic system panic when pickup call with SysTel via LINE KEY. This problem is fixed.
02	Bug fix: ARS 14307 (T240,T444,T484) Restart after disconnect an ext. calls to team (longest free) in alerting state. This problem is fixed.
TAPI	
01	Bug fix: ARS 14227 / 14270 (ICT 46, ICT 88 and ICT 880) No Answering by TAPI possible for calls initiated by transfer functions. This problem is fixed.
02	Bug fix: ARS 14314 (ICT 46, ICT 88 and ICT 880) Reactivating a parked connection by TAPI is not possible. This problem is fixed.