



RELEASE NOTE

BIANCA/BRICK-XS

27.09.1996

New System Software Release 4.2.3

The new BIANCA/BRICK-XS system software release 4.2 revision 3 corrects a couple of problems in the previous release.

When upgrading your BRICK-XS, it is recommended that you also use the most recent version of *BRICKware for Windows* and *UNIXTools*. Both can be retrieved from BinTec's FTP server at <http://www.bintec.de>

Performing the Update

You can upgrade to software version 4.2.3 using the **update** command from the SNMP shell via a remote host (i.e. using telnet, minipad, or isdnlogin) or by using the **BOOTmonitor** if you are logged in directly on the console.

Information on using the BOOTmonitor can be found in Chapter 2 of your User's Guide under *Firmware Upgrades*.

New Features

LAN Interfaces

The BRICK-XS now reports problems with the ethernet interface (e.g., unable to transmit packets due to too many collisions, cabling is not attached, etc.) to the ***biboAdmSyslogTable***.

Bug Fixes

ISDN

- Previously, if multiple isdnlogin connections were established and one connection was closed, all remaining isdnlogin connections were inadvertently terminated.

CAPI

CAPI 2.0:

- Incoming DTMF Indication now works correctly.
- CAPI_INFO_IND IE-Element was improperly coded in previous releases.