

Read Me for System Software 7.4.2 PATCH 4

This version of our system software is available for the following gateways:

- **X2301**
- **X2301w**
- **X2302**
- **X2302w**
- **R232aw**
- **R232bw**

This versions also supports the new gateways **R230a**, **R230aw** and **R232b**. It contains the following changes:

1.1 RADIUS - Sporadic Reboot

(ID 5557)

When using a RADIUS server for accounting of dialout partners, the gateway sporadically rebooted.

This problem has been solved.

1.2 HTML Wizard - Encapsulations Renamed

(ID 5662)

The encapsulations available for ATM connections were named so that the configuration information provided by ADSL providers (esp. LLC) was difficult to recognize.

This problem has been solved:

- *bridged-no-fcs* was renamed to *LLC (bridged-no-fcs)*.

- *bridged-fcs* was renamed to *LLC (bridged-fcs)*.

1.3 PPP - Connection Failure

(ID 5738)

A PPP connection attempt failed when the responder rejected the use of STAC compression during the negotiation.

This problem has been solved.

1.4 IPSec Monitoring - Sporadic Reboot

(ID 4790)

An error in the IPSec monitoring function could lead to occasional reboots.

This problem has been solved.

1.5 ISDN - Incorrect MSN Handling

(ID 5797)

Outgoing WAN numbers containing wildcards were interpreted incorrectly so that outgoing connections could not be established.

This problem has been solved.