

Read Me

System Software 9.1.10 Patch 5 BIQ

Deutsch Folgende Fehler sind in Systemsoftware 9.1.10 Patch 5 korrigiert worden:

1.1 WLAN Controller - WTP nicht korrekt verwaltet

(ID 19324)

Es konnte vorkommen, dass der WLAN Controller einen Slave Access Point nur nach einem Neustart des Slaves korrekt verwaltete.

1.2 WLAN Controller - WTP-Status falsch

(ID 19553)

Wurde ein vom WLAN Controller verwalteter WTP im Controller deaktiviert und nach einem Neustart wieder aktiv, so konnte es vorkommen, dass der Status eines anderen WTP zunächst falsch angezeigt wurde.

1.3 WLAN Controller - Scan nicht ausgeführt

(ID n/a)

Es konnte vorkommen, dass ein im Controller ausgelöster Scan nach Access Points nicht ausgeführt wurde.

English The following errors have been corrected in system software 9.1.10 Patch 5:

1.1 WLAN Controller - WTP not managed correctly

(ID 19324)

It could happen that the WLAN Controller managed a slave access point correctly only after the slave was rebooted.

1.2 WLAN Controller - WTP status incorrect

(ID 19553)

After a managed WTP had been deactivated by the controller and had become active again after a reboot, it could happen that the status of a different WTP was displayed incorrectly for a short while.

1.3 WLAN Controller - Scan not executed

(ID n/a)

It could happen that a scan triggered by the controller was never executed.