

Read Me

System Software 10.1.10.107 WIQ

Deutsch

Folgende Fehler sind korrigiert worden:

- **Panic (ID 20914):** Bei der Ausführung des WLAN-Controller-Assistenten konnte es zu einer Panic kommen, wenn bei der Auswahl der Schnittstelle keine Bridge-Schnittstelle gewählt wurde.
- **Cloud-NetManager-Kommunikation(ID #233):** Es konnte vorkommen, dass die Wiederaushandlung der Verschlüsselung zwischen dem Cloud NetManager und einem Access Point fehl schlug. Damit war keine Kommunikation zwischen den beiden mehr möglich.
- **Hotspot Gateway – Fehlfunktion nach Update (ID 20937):** Nach einem Update der Systemsoftware auf Release 10.1.21.100 war die Funktion des Hotspot Gateways nicht mehr gegeben.

English

The following errors have been corrected:

- **Panic (ID 20914):** When using the WLAN Controller assistant, a panic could occur if a non-bridge interface was chosen during interface selection.
- **Cloud NetManager communication(ID #233):** The renewal of encryption parameters could fail between the Cloud NetManager and an Access Point. No communication between them was possible after this had happened.
- **Hotspot Gateway – Malfunction after update (ID 20937):** After a system software update to release 10.1.21.100 the Hotspot Gateway was no longer functional.