funkwerk)))
enterprise communications

Release of the Beta – SW 7.31

Herewith the Beta Software 7.31 for the ICT Systems 46 / 88 / 880 is released.

The Beta SW 7.31 is exclusively a Bug-fix Release, please see the contents in the following table.

Firmware ICT 46

File: ICT46_V7.31 RC 01

Firmware ICT 88

File: ICT88_V7.31 RC 01

Firmware ICT 880 (rack)

File: ICT880_V7.31 RC 01

WIN-Tools

File: 7.31 Build 01

List of bug fixing and changes from Release 7.30 to Release 7.31

Nr.	Changes / Bugfixing
	SIP adaptations
	System
1.	All systemes: In case of configuration of **all** S0 interfaces of a system at the same time to internal or external, sometimes the S0-busses couldn't be initialised correctly. In this state all the dialling tones where lost.
2.	Depending on customer - specific configurations, it could come to a restart or even a stop of the system during the signalling of emty-space of the call charge accounts to the system Telefone. This behaviour depends very much on the customers configuration and could happen after several days or weeks.
	WIN - Tools
3.	During a change of the settings of the analogue a/b ports, it could happen that the WIN Tools stopped working and the program closed.
4.	The english help-file is now available and up to date with version 7.30 **Hinweis:** Die neuen WIN Tools werden kurzfristig auf der homepage zum Download verfügbar sein
	VoVPN – Gateway
	System - telephones
	Adaptations of analogue trunks (POTS) for export
	New functionality
	DECT
	Trunk lines
	Miscellaneous telephony
	Network

Service

Applications

General details

Open – but known problems

Hints for additional informations in the FAQ area of the FEC homepage