**funkwerk)))**
enterprise communications

# Release of the Beta – SW 7.32

Herewith the Beta Software 7.32 for the ICT Systems 46 / 88 / 880 is released.

The Beta SW 7.32 is exclusively a Bug-fix Release, please see the contents in the following table.

## Firmware ICT 46

**File:**      ICT46_V7.32  RC 02

## Firmware ICT 88

**File:**      ICT88_V7.32  RC 02

## Firmware ICT 880 (rack)

**File:**      ICT880_V7.32  RC 02

## WIN-Tools

**File:**      7.31 Build 02

List of bug fixing and changes from Release 7.31 to Release 7.32

| Nr. | Changes / Bugfixing |
|---|---|
| | **SIP adaptations** |
| | |
| | **System** |
| 1. | The internal ringing supervision timer for all phones / terminals (except of IP system phones) has been changed from currently 3 minutes to future 10 minutes. This improvement keeps special requests for e.g. medical practices. |
| 2. | Sporadic system restarts during team calls with many involved IP system phones because of high amount of system status messages. |
| 3. | Sporadic system restarts during 3-pty-conference with simultaneous TAPI monitoring. |
| 4. | Improving the call signalling at analogue ports: Partially the call signalling was not switch off after accepting the call. |
| | |
| | **WIN - Tools** |
| | |
| | |
| | **VoVPN – Gateway** |
| | |
| | **System - telephones** |
| | |
| | **Adaptations of analogue trunks (POTS) for export** |
| | |
| | **New functionality** |
| | |
| | **DECT** |
| | |
| | **Trunk lines** |
| | |

| Miscellaneous telephony |
|---|
|  |

| Network |
|---|
|  |

| Service |
|---|
|  |

| Applications |
|---|
|  |

| General details |
|---|
|  |

| Open – but known problems |
|---|
|  |

| Hints for additional informations in the FAQ area of the FEC homepage |
|---|
|  |