Entry-Id	Status	Fehlerbezeichnung
15617	Assign	hybird F50: VoiceMailBox; while recording a message to the VB from ISDN Ext. a noise is hearable
15680	Assign	Hybird F50: Outgoing call via SIP provider is delayed
15805	Assign	hybird F50 - Panic & StackTace after a service-call, if service access is disabled
15422	Investigate	hybird F50:VoiceBox records from analouge phone intern has strange noise
15890	Investigate	hybird F50 - No audio connection after automatic Call Pick-up with MoH in team
15894	Investigate	hybird F50 - No audio at the second "call through" connection over VoIP, when the first "call through" disconnected
15467	More Info	hybird F50 - LED "SD Card", no flickering during read / write access
15666	More Info	hybird F50 - Panic while assigning a new detected OpenStage 40 phone