List of solved Reports

ARS	DEV:ER	Status	Prio	Error Description
	15467	closed	lowly	hybird F50 - LED "SD Card", no flickering during read / write access
	15609	closed	medium	hybird F50 - VPN Assistant, wrong profile for phase 2
	15610	closed	lowly	hybird F50 - VPN Assistant, wrong multi-proposals for phase 2
	15787	closed	medium	hybird F50 - FCI - All PPP based WAN-Interfaces are not selectable in VoIP->Settings->Locations->Interfaces selectbox
	15805	closed	medium	hybird F50 - Panic & StackTace after a service-call, if service access is disabled
	15832	closed	medium	F50: SSH service call via bad connection does not load FCI
	15865	closed	lowly	hybird F50 - Problems with fax over VoIP providers
	15874	closed	lowly	hybird F50: GUI Message System Operation, Window has a grey background should be light orange
	15877	closed	medium	hybird F50: GUI Warning abt Uploaded OST Firmware to the SD Card
38	15925	closed	medium	hybird F50 - FV Umlaut in Display ID is not sent correctly
39	15942	closed	medium	hybird F50: ID 39: FV Display does not show name after call has been forwarded
43	15956	closed	medium	hybird f50: ID 43: phone type isn't shown in maintenance - system phones - firmware files
	15975	closed	medium	hybird F50 - After transfer to busy extension with access authorization "internal" does not recall Integration of Online Help

List of field test relevant "open issues"

ARS	DEV:ER	Status	Prio	Error Description
	15422	Investigate	lowly	hybird F50:VoiceBox records from analouge phone intern has strange noise
	15607	Assign	medium	hybird F50 - No MoH with automatic call pick-up with MoH in team, if compressed codecs are used
	15617	Assign	lowly	hybird F50: VoiceMailBox; while recording a message to the VB from ISDN Ext. a noise is hearable
	15680	Assign	medium	Hybird F50: Outgoing call via SIP provider is delayed
	15890	Investigate	medium	hybird F50 - No audio connection after automatic Call Pick-up with MoH in team
	15894	Integrate	high	hybird F50 - No audio at the second "call through" connection over VoIP, when the first "call through" disconnected
36	16004	Integrate	lowly	Hybird F50: ID 36: Configure OST for no offering CCNR
44	15961	More Info	medium	hybird F50: Id: 44 time controlled sw update to octophon does not work
45	15962	More Info	medium	hybird F50: ID 45: CTI outgoing calls to caller and callee at the same time
36	16004	Integrate	lowly	Hybird F50: ID 36: Configure OST for no offering CCNR