



---

# RELEASE NOTE

## BIANCA/BRICK-XS

10.10.1996

### New System Software Release 4.2.4

The new BIANCA/BRICK-XS system software release 4.2 revision 4 corrects a problem with CAPI 2.0 and incoming X.31 calls in previous releases.

- For incoming calls using the X.31 protocol (X.25 on the D channel) the CAPI was not signalled with a CONNECT\_B3\_IND message. This has been fixed and now works as specified.

#### Performing the Update

You can upgrade to software version 4.2.4 using the **update** command from the SNMP shell via a remote host (i.e. using telnet, minipad, or isdnlogin) or by using the **BOOTmonitor** if you are logged in directly on the console.

Information on using the BOOTmonitor can be found in Chapter 2 of your User's Guide under *Firmware Upgrades*.