

Read Me System Software 7.1.1 PATCH 17

This version of our system software is a non-IPSec version and available for the following gateways:

- **X1000**
- **X1200**
- **X3200**

It solves the following problem:

PPP - Connection Reject

(ID 3582)

An LCP Protocol-Reject was caused by an uncompressed Address Protocol header in the CHAP or PAP Authentication Response sent by the Bintec gateway. This was not RFC compliant.