

Read Me System Software 7.2.1 PATCH 1

English This Read Me applies to the following products only: **X1x00 II**, **X2404** and **X4100**.

In **System Software 7.2.1**, the 10 Mbit/s Ethernet interface of a gateway remained down if it was connected to another Ethernet interface that did not support autonegotiation.

The problem has been solved in **System Software 7.2.1 PATCH 1**.

Deutsch Dieses Read Me betrifft lediglich die folgenden Geräte: **X1x00 II**, **X2404** und **X4100**.

In **Systemsoftware 7.2.1** blieb das 10 Mbit/s Ethernet Interface eines Gateways inaktiv, wenn es mit einem anderen Ethernet Interface verbunden wurde, das keine Autonegotiation unterstützt.

Das Problem ist in **Systemsoftware 7.2.1 PATCH 1** gelöst.