

## **Read Me**

### **System Software 7.9.4 PATCH 8**

**Deutsch** Diese Version unserer Systemsoftware ist für Geräte der **RS-Serie** verfügbar.

Folgende Änderungen sind vorgenommen worden:

#### **1.1 IPsec - Durchsatzprobleme**

**(ID 13405)**

Da es vorkommen konnte, dass der Authentisierungs-Hash auf zwei Message-Blocks verteilt wurde, konnte es zu Problemen beim erreichten Datendurchsatz kommen.

Das Problem ist gelöst.

#### **1.2 TACACS+ verfügbar**

**(ID 13573)**

TACACS+ war bisher auf den Geräten der RS-Serie nicht verfügbar.

Das Problem ist gelöst.

#### **1.3 ISDN - Verbindungsprobleme**

**(ID 13487)**

Aufgrund eines Problems im D-Kanal konnten ISDN-Verbindungen gestört sein.

Das Problem ist gelöst.

**English** This version of our system software is available for gateways of the **RS Series**.

The following changes have been made:

## **1.1 IPsec - Throughput Issues**

**(ID 13405)**

Since it could happen that the authentication hash was split across two message blocks, there were occasional issues with the data throughput achieved.

The problem has been solved.

## **1.2 TACACS+ available**

**(ID 13573)**

TACACS+ was not available on the devices of the RS Series.

The problem has been solved.

## **1.3 ISDN - Connection Issues**

**(ID 13487)**

Due to a problem with the D-channel, ISDN connections were occasionally malfunctioning.

The problem has been solved.