

Bekannte Probleme / Known Issues RXL 12500

Deutsch



Die folgenden Hinweise beziehen sich auf Version 7.10.1 unserer Systemsoftware für **RXL 12500**.

1.1 USB-Anschluss

Die USB-A-Schnittstelle (mit der Bezeichnung "USB") zum Anschluss eines UMTS-Modems wird derzeit noch nicht unterstützt,

Beachten Sie, dass es sich hierbei nicht um die den USB-Konsolenanschluss handelt, der voll funktionsfähig ist.

1.2 Englische Online-Hilfe

Die englische Online-Hilfe ist noch nicht verfügbar.

1.3 Konfigurationsgröße

Konfiguration von 32 MB und mehr können derzeit nicht per TFTP in das Gerät geladen werden.

English



The following notes apply to version 7.10.1 of our system software for **RXL 12500**.

1.1 USB Port

The USB A port (labelled "USB") for connecting an UMTS modem is not yet supported.

Note that this does not apply to the USB Console connection which is fully functional.

1.2 English Online Help

English online help is not yet available.

1.3 Configuration Size

Configurations of a size of 32 MB and larger cannot be uploaded to the device via TFTP.