

Read Me

System Software 9.1.10 Patch 3 BLM

Deutsch Folgende Fehler sind in Systemsoftware 9.1.10 Patch 3 korrigiert worden:

1.1 PKI - Probleme mit PKCS#12

(ID 18911)

Wurde in einer PKI PKCS#12 zur Authentisierung verwendet, konnte es zu Problemen beim Aufbau von IPSec-Verbindungen aufgrund gescheiterter Authentisierung kommen.

1.2 Media Gateway - Panic

(ID 18996)

Während des Betriebs als Media Gateway konnte es zu einem Stack Trace mit Neustart des Geräts kommen.

1.3 SIP - Verbindungsabbruch

(ID 18964)

Es konnte zum Abbruch von SIP-Verbindungen kommen.

English The following errors have been corrected in system software 9.1.10 Patch 3:

1.1 PKI - Problems with PKCS#12

(ID 18911)

If PKCS#12 was used for authentication in a PKI, there could be issues with establishing IPSec connections because of authentication failures.

1.2 Media Gateway - Panic

(ID 18996)

During operation as media gateway there were occasional stack traces and reboots of the device.

1.3 SIP - Disconnects

(ID 18964)

There were occasional interruptions of SIP connections.