

# Release Notes System Software 3.2.1.4

### Content

1	Note	. 1
2	Error corrections	. 1
3	Known Issues	1

#### 1 Note

This version is only available for **W2044ax**, **W2022ax** and **APR2044ax**. Please note that the **W2022ac** and **W2044ac** access points use the same release numbering and are also functionally comparable. However, the system software files are different. The software image is now provided on the update server in two different formats:

- .img: Files with this file extension are used as before for updating the access point directly via the user interface or for updating via the WLAN controller.
- .tgz: Files with this file extension are required when updating the access points via Cloud Net Manager (Cloud Net Manager version 5.1.4 or higher).
   For this purpose, this file must be loaded into the Cloud Net Manager software library.

## 2 Error corrections

- ER#6050 A security update for <u>CVE-2022-2068</u> has been integrated.
- If the access point was managed via a WLAN controller and if WPA3 was used as the security mode in combination with enabled 802.11r, then WLAN clients were incorrectly displayed in WLAN controller client monitoring without a security mode if they used WPA3-PSK as the security mode. This error has been fixed and the security mode of the connected WLAN clients is now also correctly transmitted to the WLAN controller in this case.

#### 3 Known Issues

 The AP Steering and Radio Resource Management (802.11k) settings are included in the configuration interface but have no function in this release.