

Release Notes 42.210

DECT 150

1. Änderungen

- Das neue DECT Mobilteil **elmeg D150R** wird unterstützt
- **Web-Konfigurator:** Firmware-Update-Seite kann durch die Provisionierung ausgeblendet werden
- **SIP** Session Timers implementiert gemäß RFC 4028
- **Blind Transfer:** Verbessertes Verhalten, die Gespräche von einem Teilnehmer werden ohne Rückfrage zu einem anderen Teilnehmer übertragen

2. BugFixes:

- **NL – RoutIT:** 2 – 3 Sekunden Verzögerung nach der Anrufübernahme

3. Bekannte Probleme:

- Nach der Abmeldung des Mobilteils wird ein Neustart durchgeführt
- Das Kopieren der Telefonnummer aus der Anrufliste in das Verzeichnis ist nicht immer möglich, das Telefon geht in der Ruhezustand
- Nach dem Firmware-Update wird die System-PIN auf den Standardwert '0000' gesetzt

1. Improvements:

- New handset support **elmeg D150R**
- **Web Configurator:** Firmware update page can be hidden by provisioning parameter
- **SIP Session Timers** implemented according to RFC 4028
- **Blind transfer:** Improve behavior when device is blind transferred by another party

2. BugFixes:

- **NL – RoutIT:** 2 – 3 seconds of audio path after call pickup

3. Known issues:

- Reboot occurs after deregistering handset
- Copy phone number from call list to directory is not always possible – phone goes back to idle
- After firmware update system PIN is changed to default '0000'