

Release Notes 02.01.00

elmeg IP120

1. BugFixes:

- Beim Ändern der Headset-Lautstärke wird der geänderte Wert nicht gespeichert
- Neustart bei eingehenden Anruf
- Nach 15 Minuten wird die Verbindung unterbrochen und Neustart wird angezeigt
- Das Gerät "friert" nach dem eingehenden Anruf ein
- XML Dir: Scrollen durch die Suchergebnisse ist nicht möglich
- Neustart während eines eingehenden Anrufs
- Das Gerät "friert" ein
- [DND] Eingehender Anruf blockiert manche Tasten am Gerät
- Umschalten über Rückfragetaste nicht möglich

2. Upgrade Instruktion:

Download von der Webseite

Hochladen auf die elmeg Hybird -> Telefon-Wartung -> Telefon -Upgrade -> Patch Release -> lokale Einstellungen im Telefon bleiben erhalten

3. Bekannte Probleme:

- ...

4. Erweiterungen:

- ...

1. BugFixes:

- Headset volume does not stay on adjusted setting
- Reboot on incoming call
- After 15-minutes call connection was broken / additionally reboot appears
- Device frozen after incoming call
- XML Dir: Scrolling through search results is not possible
- Rebooting during incoming call
- Device freezes
- [DND] Incoming call blocks some keys on HW
- Toggling via consultation key not possible

2. Upgrade Instructions:

Download from the Web site

Upload on the elmeg Hybird -> Phone Maintenance -> Phone upgrade -> Patch Release -> Local settings in phone are retained

3. Known issues:

- ...

4. Enhancements:

- ...