

Read Me

System Software 7.5.1 PATCH 6

This version of our system software is available for the following gateways:

- **WI-Serie**
- **Wx002-Serie**
- **Rxx00-Serie**
- **TR200**

It contains the following changes:

1.1 FCI - Display of IPsec Parameters

(ID n/a)

The values for Phase 1 Diffie Hellman Group and the settings of Phase 2 PFS were displayed as numerical values that did not immediately reveal their meaning.

The problem has been solved.

1.2 FCI - Obsolete Field in ATM Menu

(ID n/a)

There was an obsolete field for bridging entries in the menu WAN -> ATM -> ATM Profiles.

The problem has been solved.

1.3 PABX - Automatic Route Selection Disables Call by Call

(ID n/a)

Automatic Route Selection disabled the use of call by call connections.

The problem has been solved.

1.4 WLAN - Enhancements

(ID n/a)

The WLAN subsystem was enhanced, removing memory management errors (reboots due to memory loss), auto configuration errors (incorrect configurations and reboots) and problems with the overall connection quality.