

elmeg T484, Version 1.12 RC2

The software version 1.12 is mainly bug-fix software; the content is described in the following table.

Firmware elmeg T484

File: t484_v112_rc2.fwr

WIN-Tools

Unchanged, please use version 2.05.

Table of errors and changes from version 1.10 to version 1.12

| No. | Changes / Bug fixing |
|-------------------------|--|
| SIP improvements | |
| 1. | Several problems solved with some SIP-Providers Toplink, 1&1, QSC |
| 2. | CLIP to a SIP Provider in case of call forwarding The complete number will now be transferred correctly. |
| 3. | VoIP connections to internal voice applications with DISA function DTMF dialling will be supported for incoming VoIP connections connected to a voice application (e.g. Auto Attendant with DISA). |
| | |
| System | |
| 4. | LCR – improvements regarding Call forwarding in conjunction with SIP Providers / trunks |
| 5. | Call rerouting on Busy (analogue extensions) Only if configured a call rerouting on busy will be carried out. |
| | |
| | |
| | |