

elmeg T484, Version 1.13 RC1

The software version 1.13 is mainly bug-fix software; the content is described in the following table.

Firmware elmeg T484

File: t484_v113_rc1.fwr

WIN-Tools

Unchanged, please use version 2.05.

Table of errors and changes from version 1.12 to version 1.13

No.	Changes / Bug fixing
SIP improvements	
1.	CLIP to a SIP Provider using accounts with multiple MSNs Using Accounts with multiple MSNs the number, configured within the WIN-Tools, will be signalled.
System	
2.	ISDN B channel bonding Bonding of ISDN B channels will be supported for ISDN data and ISDN internet applications (bonding two ISDN lines 64k to one connection to 128k).
	

elmeg T484, Version 1.12 RC2

The software version 1.12 is mainly bug-fix software; the content is described in the following table.

Firmware elmeg T484

File: t484_v112_rc2.fwr

WIN-Tools

Unchanged, please use version 2.05.

Table of errors and changes from version 1.10 to version 1.12

No.	Changes / Bug fixing
SIP improvements	
1.	Several problems solved with some SIP-Providers Toplink, 1&1, QSC
2.	CLIP to a SIP Provider in case of call forwarding The complete number will now be transferred correctly.
3.	VoIP connections to internal voice applications with DISA function DTMF dialling will be supported for incoming VoIP connections connected to a voice application (e.g. Auto Attendant with DISA).
System	
4.	LCR – improvements regarding Call forwarding in conjunction with SIP Providers / trunks
5.	Call rerouting on Busy (analogue extensions) Only if configured a call rerouting on busy will be carried out.