

Readme for System Software 7.1.1 PATCH 16 (Non-IPSec Version)

The following changes have been made to System Software 7.1.1 in order to improve performance and stability. Make sure to check the Release Notes of the major release corresponding to this PATCH release for specifics concerning update procedures and restrictions.

1) Local HTTP Login Attempt Leads to Stack Trace (ID 4018)

When an local HTTP access was attempted with overly long authentication data, the gateway occasionally rebooted.

This problem has been solved.