

Read Me System Software 7.2.2 PATCH 1

English In **System Software 7.2.2** the TCP Download Rate Control (TDRC) was not working as expected. The problem has been identified and solved in **System Software 7.2.2 PATCH 1**.

Deutsch In **Systemsoftware 7.2.2** arbeitete die TCP Download Rate Control (TDRC) nicht wie erwartet. Das Problem ist identifiziert und in **Systemsoftware 7.2.2 PATCH 1** behoben worden.