

Read Me

System Software 7.9.1 PATCH 3 / 7.9.2 PATCH 3

Deutsch Diese Version unserer Systemsoftware ist für Geräte der **R(T)xxx2-Serie** verfügbar.

Folgender Fehler ist beseitigt worden:

1.1 Lizenzmechanismus fehlerhaft

(n/a)

Aufgrund eines Fehler in der Systemsoftware konnten gültige Lizenzen vom Gateway nicht erkannt werden.

Beachten Sie, dass die ausgegebenen Lizenzen gültig sind und lediglich aufgrund eines Fehlers in der Systemsoftware nicht aktiviert werden konnten. Nach der Aktualisierung der Systemsoftware können die Lizenzen aktiviert und verwendet werden.

English This version of our system software is available for gateways of the [R\(T\)xxx2 Series](#).

The following error has been removed:

1.1 License Mechanism Faulty

(n/a)

Due to a system software error, the gateway was unable to identify valid licenses.

Note that the licenses issued are valid and just could not be activated due to an error in the system software. After upgrading the system software, the licenses can be activated and will be functional.