

# Release Notes 3.19.0

## elmeg IP620 / IP630

---

### 1. Was ist neu?

- Die Konfiguration des BLF ist auf dem Gerät selbst durch einen langen Tastendruck möglich.

### 2. Verbesserungen

- Die Handhabung und Stabilität der Konfigurationsoberfläche wurde verbessert.
- Übersetzungen sind aktualisiert worden.

### 3. Fehlerkorrekturen

- Die Telefone sendeten keine SUBSCRIBE-Pakete an die Telefonanlage.
- Notrufnummern wurden nicht wiederhergestellt.
- Park + Retrieve funktionierte nicht auf einer Asterisk-Telefonanlage.
- USB- und Bluetooth-Headset hatten Probleme mit Türstationen.

### 1. What is new?

- The configuration of the BLF is possible on the device itself by a long pressing a key.

### 2. Improvements

- The handling and stability of the configuration interface has been improved.
- Translations have been updated.

### 3. Error corrections

- Maxwell did not send SUBSCRIBE packets to PBX.
- Emergency numbers were not restored.
- Park + Retrieve did not work on an Asterisk PBX.
- USB and Bluetooth headset had issues with door stations.