

# Release Notes System Software 2.5.1.4

1	Note	2
	New functions	
	Error corrections	



# **Release 2.5.1.4**

#### 1 Note

This version is only available for W2044ax, W2022ax and APR2044ax.

### 2 New functions

- Release 2.5.1.4 supports the new **APR2044ax** access point. The **APR2044ax** is a special version of the W2044ax and is intended for use in rail vehicles.
- With Release 2.5.1.4, the W2044ax access point can be managed via the Cloud Net Manager in addition to configuration via its own GUI and the WLAN controller.

## 3 Error corrections

- **(ER#5528)** If the **LED mode** of the access point was set to *Off*, this setting was not retained after a reboot.
- The display of the received signal strength for WLAN devices registered at the access point was not correct over all antennas present in the access point.