

Read Me

System Software 10.1.10.101/102 WIQ

Deutsch

Folgende Fehler sind korrigiert worden:

- **System – Panic (ID 20587):** Es kam sporadisch zu einer Panic und einem Neustart des Geräts.
- **System – Geräte nicht erreichbar (ID n/a):** Es konnte vorkommen, dass ein Gerät nach einem Neustart nicht erreichbar war.
- **WLAN – Verbindungsprobleme (ID 20550):** Es konnte vorkommen, dass sich bestimmte WLAN Clients nicht verbinden konnten.
- **System - Update-Probleme (ID 20395):** Bei Verwendung mehrerer Bridge-Gruppen traten bei einem Update der Systemsoftware auf Version 10.1.10 Probleme auf.

English

The following errors have been corrected:

- **System – Panic (ID 20587):** The device sporadically panicked and rebooted.
- **System – Devices not accessible (ID n/a):** It happened that a device was not accessible after a reboot.
- **WLAN – Connections issues (ID 20550):** It happened that specific WLAN clients were unable to connect.
- **System – Update problems (ID 20395):** The use of multiple bridge groups could lead to problems after an update to system software 10.1.10.