

Read Me

System Software 7.8.3 PATCH 1

This version of our system software is available for the following gateways:

■ **W1002n**

The following changes have been made:

1.1 FCI - Irrelevant Parameters Removed

(ID 11413)

A number of parameters that are not supported by the 11n chipset have been removed from the FCI.

1.2 FCI - Missing Texts Added

(ID n/a)

A number of texts for certain parameters were missing in the German version of the FCI.

The problem has been solved.

1.3 Shell - Command not Executed Properly

(ID 11448)

Command execution on the shell malfunctioned if the batch included a command which the shell interprets as an external command.

The problem has been solved.

1.4 FCI - Wrong WLAN Channel Displayed

(ID 11425)

When used in "Access Point" mode, the summary of the radio settings could show a wrong WLAN channel (the configured one instead of the one actually used).

The problem has been solved.

1.5 FCI - Invalid Parameter

(ID 11427)

The FCI allowed choosing the invalid security setting "WPA-PSK" for ad hoc connections.

The problem has been solved.

1.6 SIF - Stacktrace during Configuration

(ID 11405)

Upon configuring the SIF services, a stacktrace occurred and the Setup was terminated.

The problem has been solved.

1.7 IGMP - Cache Entries not Removed

(ID 11356)

Cache entries of the IGMP proxy are not properly removed.

The problem has been solved.